

- PEGAS<sup>®</sup>**  
*craftap<sup>3</sup>*

The diagram illustrates the installation requirements for the PEGAS craftap³ device. It shows the device's footprint with various mounting holes and handles.

**Dimensions:**

  - Total width: 65mm (2.56")
  - Rear side width: 35mm (1.38")
  - Top handle offset: 13mm (0.51")
  - Left handle offset: 129mm (5.08")
  - Central hole diameter: Ø 70mm (2.75")
  - Inner square hole pattern side length: 106mm (4.17")
  - Outer circle diameter: 254,5mm (10.0")
  - Vertical distances from top edge: 115mm (4.53"), 76mm (2.99")
  - Horizontal distance from left edge to inner square center: 106mm (4.17")

**Holes and Drilling Locations:**

  - Ø 10mm (0.39") holes: 4 holes (indicated by a label pointing to four small circles).
  - Ø 18mm (0.70") hole: One hole (indicated by a label pointing to one medium circle).
  - Drilling location: Indicated by hatched areas (indicated by a legend box labeled "Drilling location").

**Labels:**

  - Rear side
  - Face side

**Instructions:**

  - Place the stencil on the place where you want the device to be installed.
  - Make sure that installation place matches to the dimensions specified on the picture and inserted on the stencil.
  - Use a pencil to mark the outlines of the stencil onto the surface where you will mount the device. Broken line indicates the device door in the open position and urging the handle assembly in the extreme positions.
  - Using a 10, 13, 18, 70 mm drill or any other suitable instrument, perform the appropriate holes.